

















<b>MAKE:</b> HYUNDAI	<b>HYU-51</b>	<b>HYU-52</b>
<b>TYPE:</b> Terracan / Santa Fe		
	<b>MODEL:</b> Terracan HP (3.5L V6, 2.9L) <b>YEAR:</b> 2001 on	<b>MODEL:</b> Santa Fe (2.7L V6, 2.4L, 2.0L TD) <b>YEAR:</b> 2000 – 05/2006

 FRONT 	TYPE	QTY	PART NUMBER
<p><b>Terracan</b></p> <p><b>TORSION BAR</b></p>  <p>Type 'D'</p> <p>Heavy Duty Rate Increased Length 1275mm</p>	D	1	<b>TB25-1248</b> (Pair)
<p><b>SHOCK ABSORBER</b></p>  <p>Type 'A' 'B' 'C'</p> <p>Heavy Duty Gas</p>	B	2	<b>GS45-087</b>

 FRONT 	TYPE	QTY	PART NUMBER
<p><b>Santa Fe</b></p> <p><b>COIL SPRING</b> Type 'C'</p>  <p>Linear Rate Standard Height</p> <p>Linear Rate Raised Height (20mm Lift)</p>		1	<b>C25-026</b> (Pair)
		1	<b>C25-028</b> (Pair)

 REAR 	TYPE	QTY	PART NUMBER
<p><b>Terracan</b></p> <p><b>COIL SPRING</b> Type 'C'</p>  <p>Linear Rate Standard Height (10mm Lift)</p> <p>Linear Rate Raised Height (45mm Lift) Medium Load to GVM</p>		1	<b>C43-047V</b> (Pair)
		1	<b>C43-043V</b> (Pair)
<p><b>SHOCK ABSORBER</b></p>  <p>Type 'A' 'B' 'C'</p> <p>Heavy Duty Gas</p>	B	2	<b>GS59-223</b>

 REAR 	TYPE	QTY	PART NUMBER
<p><b>Santa Fe</b></p> <p><b>COIL SPRING</b> Type 'C'</p>  <p>Linear Rate Standard Height</p> <p>Linear Rate Raised Height (35mm Lift)</p>		1	<b>C25-027</b> (Pair)
		1	<b>C25-029</b> (Pair)
<p><b>SHOCK ABSORBER</b></p>  <p>Type 'A' 'B' 'C'</p> <p>Heavy Duty Gas</p>	B	2	<b>GS59-940</b>