

**MAKE:** LANDROVER      **TYPE:** Discovery III

**MODEL:** LR3              **YEAR:** 01/2005 on

**DETAIL:** 2.7L V6 TD, 4.0L V6 Petrol  
Coil Spring Models Only

LAND-59



<b>FRONT</b>		<b>TYPE</b>	<b>QTY</b>	<b>PART NUMBER</b>
<b>COIL SPRING</b> Type 'C' 			1	<b>C51-066</b> (Pair)
<p style="text-align: center;">Linear Rate Raised Height (45mm Lift)</p>				
<b>SHOCK ABSORBER</b> <p>Type 'G' 'H' 'K'</p>			2	<b>GS51-120</b>
<p style="text-align: center;">Heavy Duty Gas</p>		K		

<b>REAR</b>		<b>TYPE</b>	<b>QTY</b>	<b>PART NUMBER</b>
<b>COIL SPRING</b> Type 'C' 			1	<b>C51-067</b> (Pair)
<p style="text-align: center;">Linear Rate Raised Height (45mm Lift)</p>				
<b>SHOCK ABSORBER</b> <p>Type 'G' 'H' 'K'</p>			2	<b>GS51-121</b>
<p style="text-align: center;">Heavy Duty Gas</p>		K		